

Statement of Evidence:

D061

North Quarter Corner of Section 6, Township 38 North, Range 31 West, East Langola Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

12" Blk Oak	N 67 1/4 E	339 links
10" Blk Oak	N 66 W	146 links

1996 Comstock & Davis searched for corner and no monument was found. Corner was determined obliterated and established at the intersection of fence lines north, east, and west. A ½" iron pipe was set on the north side of a 4" x 8" wood corner fence post. Certificate of Location was filed in Morrison County by Bruce Grivna, LS 17253, (Doc. No. 0370593).

2002 No resurvey information was found on this corner in the Benton County records.

2006 At this location neither the original GLO corner post nor bearing or line trees were found. Westwood Professional Services, Inc. found a ½" iron pipe capped 17253 at the intersection of fences east, west, and north per document number 370593. This corner location fits the original GLO distance west within 2 feet assuming three 2-pole busts and east within 12 feet assuming one 2-pole bust. The projection of occupation from the north in Section 31 and from the south in Section 6 falls 33 to 40 west of the found iron pipe. Several half-miles along the north County line measure approximately 33 or 66 feet (2 or 4 poles) long of 2640. By projecting the occupation of the north-south quarter lines from the north and south, both the east and west half miles would measure 4 poles long. The area 33 feet west of the found iron needs to be searched and occupation to the north and south needs to be located further.

County Coordinates to ½" iron pipe capped 17253

NAD 83 (1996 Adjustment)

N- 196239.905

E- 448696.587

2007 Searched area west of iron found in 2006 and found a ½" iron pipe without a cap. This position fits the GLO distance west within 10 feet assuming a 2-pole bust and east within 4 feet assuming a 4-pole bust. Additional investigation needs to be completed before accepting either corner position.

County Coordinates to ½" iron pipe without a cap

NAD 83 (1996 Adjustment)

N- 196239.354

E- 448672.207