

Certified, Filed and or Recorded on  
Nov. 04, 2008 AT 12:28PM

Signed: BN

MARILYN J NOVAK G V I

BENTON COUNTY MINNESOTA

MARILYN J NOVAK

COUNTY RECORDER

## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH EAST

Corner of Section 16, Township 38, Range 29


4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-28-08 found a 1/2" OPEN IRON PIPE

left monument as found  lowered monument  removed monument (explain)

On \_\_\_\_\_ placed an \_\_\_\_\_



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature BN  
Deputy County Surveyor  
License No. 43932

Date: 11/3/08

Statement of Evidence:

B162

Northeast Corner of Section 16, Township 38 North, Range 29 West, Alberta Township,  
4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and  
bearing trees were recorded.

8" Tamarack	N 35 E	144 links
6" Tamarack	N 25 W	198 links

1912 County Surveyor's Record Book 2, page 254, notes new bearing tie:

6" Stone	N 38 W	116 links
(bottle under a stone)		

*NOTE: Believe this is wrong township!*

1932 County Engineer's Notebook No. 66 contains road survey for SAR 3 running  
south to north. Notes show corner marked by a hub with fence line east and road  
west. Ties:

TP	SW	35.0'
Cor. FP	NW	34.9'

Same ties listed in County Surveyor's Record Book 2, page 268.

1951 County Engineer's Notebook No. 190 contains survey of SAR No. 3 running from  
the south to north. Corner is shown as a hub in road with town road running west  
9 feet south and on fence line running east. Ties:

4 <sup>th</sup> FP	E	61.9'
TP	SW	45.8'

Same ties listed in County Surveyor's Record Book 2, page 268.

1978 Paul Wellen, LS 10461, found a  $\frac{1}{2}$ " iron pipe at the centerline of roads  
north/south/west and a fence line east. He replaced it with a  $\frac{1}{2}$ " iron pipe and  
filed a Certificate of Location (#151867). His notes give measurement of 2694.85  
feet to the East  $\frac{1}{4}$  corner of Sec. 9.

2008 Westwood Professional Services, Inc. found  $\frac{1}{2}$ " iron pipe near intersection of  
roads north/south/west and on line with fence to east. Measured 2694.68 to E1/4  
corner of Section 9 and found one of Wellens 1978 ties.  $\frac{1}{2}$ " iron pipe is accepted  
as marking the obliterated position for this corner.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-185904.898

E-526336.311

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

N. E. Corner of Section 16, Township 38, Range 29,   P.M.  
STATE OF MINNESOTA, County of Benton


At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

## SKETCH OF REFERENCE TIES



Filed under S. W. Corner Section 10, T38 R 29

Certificate #151867

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

---

SIGNATURE	DATE
-----------	------

Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE REGISTER OF DEEDS  
County of \_\_\_\_\_  
I hereby certify that this document was filed in  
the Reg. of Deeds office at \_\_\_\_\_ .M. on the  
\_\_\_\_ day of \_\_\_\_\_ A.D., 19 \_\_\_\_  
Register of Deeds \_\_\_\_\_  
By \_\_\_\_\_, Deputy  
DOCUMENT NO. \_\_\_\_\_

Should BE NORTH EAST corner Section 16, T 38 R 29  
Index No. \_\_\_\_\_

## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I did set the Southwest Corner of Section 10, Township 38, Range 29, 4 P.M.


STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

On 10-17-78 found a 1/2" iron pipe, on the center line of north-South County <sup>DATE</sup> Road No. 3 on the center line of west twp. road & on east fence line  left monument as found,  lowered monument,  removed monument (explain)

On \_\_\_\_\_ placed a permanent marker consisting of 1/2" iron pipe

### SKEETCH OF REFERENCE TIES



Refer to next page

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Paul E. Steller

SIGNATURE

DATE

Registration No. 10461

Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

*County Recorder*  
OFFICE OF THE REGISTER OF DEEDS  
County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 10 A.M. on the 26th day of March A.D., 1979

Register of Deeds T. A. Johnson

By \_\_\_\_\_, Deputy


DOCUMENT NO. 151867

## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 17 day of October, 1978 I did set the Southwest corner of Section 10, Twp. 38, Rg. 29, Benton County, Minnesota, which was evidenced by a 1/2" iron pipe, on the center line of north-south County Road No. 3, on the center line of west township road, and on east fence line.

I further certify that in order to perpetuate said corner I did at the exact location thereof place a permanent marker consisting of a 1/2" iron pipe and that

I did establish witness or reference monuments as shown below:



151867

Office of the County Recorder,  
Benton County, Minn.

I hereby certify that the within instrument was filed for record in this office on the 26th day of March, 1979, at 10 a.m.

I hereby certify that the above is true and correct and that I am a registered Land Surveyor under the laws of the State of Minnesota.

Frank Miller

Minn. Registration No. 10461

F. G. Johnson  
County Recorder

By \_\_\_\_\_ Deputy.