

428596

Certified, Filed and or Recorded on  
April 03, 2018 1:30 PM

BENTON COUNTY MINNESOTA  
CHERYL L. KANTOR  
COUNTY RECORDER

By: BS

6 - 4 - 1

## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 4, Township 38, Range 31  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_

left monument as found       lowered monument       removed monument (explain)

On 2-15-12 placed on 1/2" IRON PIPE WITH RLS CAP 19552



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock  
Benton County Surveyor  
License No. 19552

Date: 3/29/2018

PAGE 1 OF 2

Benton County Surveyor's Office  
Jerome C. Wittstock, County Surveyor  
Minnesota License No. 19552

**Statement of Evidence:**

**D043**

East Quarter of Section 4, Township 38 North, Range 31 West, East Langola Township,  
4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

15" Tamarack	S 75 1/2 E	400 links
8" Bur Oak	N 75 1/2 W	487 links

1916 County Surveyor's Record Book 2, page 31, and Record Book A, Map No. 26, show a survey of Section 3 by J.P. Soderstrum. Notes show no sign of corner found. He measured 81.50 chains (5379.0 feet) between the section corners and shows corner at lost position 39.92 chains (2634.72 feet) north of SE corner and 41.58 chains (2744.28 feet) south of NE corner.

2012 The Benton County Surveyor's Office reconstructed the 1916 survey, which among other findings found that there is a 66-foot blunder on the north half of the east line of Section 4. A 1/2" x 14" iron pipe capped 19552 was set to mark the lost position proportioned to the 1916 survey. The proportioned distance indexes well with other half mile distances, namely the east line of the Southeast Quarter of Section 3 and the east line of the Northeast Quarter of Section 9. This position also preserves the integrity of the section subdivision of Section 3 in the 1916 survey.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N- 193518.625

E- 462313.520