

**Statement of Evidence:**

**D292**

Northeast Corner of Section 29, Township 38 North, Range 31 West, East Langola Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office survey set a wood post in a mound with a pit 8 links south at the corner location.
- 1929 County Engineer's Notebook No. 54 contains road survey for CAR A (21) run north from SAR No. 12. Ties to corner:  
TP SE 58.2'  
Cor. FP E 35.0'  
(Notation dated 1944 shows found old wood stake and lists same ties as below)
- 1930 H.G. Elletson, County Engineer, shows a PI on the road alignment, near the corner location.
- 1944 County Surveyor's Record Book 2, page 138, notes a stake with the following reference ties.  
6" W. Cedar NW 74.0  
SW Cor Till Bld NE 110.6
- 1969 Carley/Lang notes on file with David Regan show an I.M. at the corner location.
- 1971 William Lunser, LS 9394, set a 1/2" pipe at the corner location. He filed a Certificate of Location (#133445) and notes a distance of 2664.63 feet to the East 1/4 corner Sec 20 and a distance of 2762.83 feet to the South 1/4 corner Sec 20.
- 1978 Paul Wellen, LS 10461, notes give a distance of 2628.54 feet to the North 1/4 corner of Section 28 and 2663.84 feet to the East 1/4 corner of Section 29.
- 1983 William Lunser replaced the 1/2" pipe with a cast iron monument. He filed a Certificate of Location (#173429).
- 2000 Sam Deleo, LS 40341, found a cast iron monument with the top broken off. He set a 1/8" drill hole in the broken off cast iron monument. He filed a Certificate of Location (#271523) and notes a distance of 2628.61 feet to the North 1/4 corner Sec 28 (CIM) and a distance of 2663.78 feet to the East 1/4 corner Sec 29 (CIM).  
Corner is shown on the following record plat: EASTSIDE ESTATES by Sam Deleo filed 7/5/2001
- 2004 Westwood Professional Services, Inc. found a broken CIM at the corner location..  
County Coordinates obtained by GPS.  
NAD 83 (1996 Adjustment)  
N-174906.482  
E-457506.360
- 2004 MN/DOT  
County Coordinates obtained by GPS  
NAD 83 (1996 Adjustment)  
N-174906.496  
E-457506.343