

Statement of Evidence:

D352

Northeast Corner of Section 35, Township 38 North, Range 31 West, East Langola, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post in a mound at the corner location.

1914 County Road Book, page 80 contains a road survey by M. J. Cleveland, District Engineer, for State Road No. 5. Survey shows corner found and road run east-west from the corner.

Undated County ties note a 3/4" iron pin, 1.5' south of centerline of east/west road and 4' west of centerline of road north with the following reference ties.

PK N end 24" CMP	NW	45.90
Rivet Hole S end 24" CMP	SW	54.85
N&D Top Tele. Ped	NE	54.00
N&D 10" Pine	SE	87.22

No Date County Surveyor's Record Book 2, page 132, shows an iron with the following reference ties.

Culvert	SW	45.6
Culvert	NW	46.4

1921 County Surveyor's Record Book 2, page 150 shows an iron with the following reference ties.
TP NW 69.8'
Cor FP S 33.0'

Notes are in Engineer's Notebooks 21 & 27, that also notes fence north and road south.

1973 William Lunser, LS 9394, found a 3/8" iron pin at the centerline of a road east/west/north and filed a Certificate of Location (#137337). A distance of 2691.77 feet is noted to the North 1/4 corner of Section 35.

1977 Paul Wollen, LS 10461, used same corner in survey in Section 26 showing a distance of 5305.09 feet to the NE corner of Section 26.

2001 Westwood Professional Services, Inc. found a 1/2" rebar at the corner location, which checked to above culvert ties and Lunser's ties.

2002 Westwood Professional Services, Inc. located monuments along County Road 2, prior to road construction, using GPS. Set an iron pipe capped #12684 at the location of the found 1/2" rebar after road construction and filed Certificate of Location (Doc. No. 293722).

County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-169636.196
E-473597.351