

Statement of Evidence:

C363

East Quarter Corner of Section 36, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded

| | | |
|------------|--------|----------|
| 8" Blk Oak | N 61 E | 19 links |
| 6" W Oak | West | 15 links |

A 10" W Oak tree was noted South 18.45 chains and a 10" Poplar North 20.76 chains

1981 Paul Wellen's, LS 10461, records show he set a RR spike in center of roads north, south, and west and in line with fence east. He measured 2627.97 feet to the NE corner and 2690.41 feet to the SE corner of Section 36. Ties:

| | | |
|---------------|------|-------|
| 4" Ash | East | 63.96 |
| 14" W. Pine | SW | 57.86 |
| Te. Ped. Post | NW | 48.86 |

2002 No resurvey information was found on this corner in the Benton County records.

2004 Danny Kron, LS 42621, found RR spike. Measured 2690.46 feet to the SE corner Section 36.

Coordinates Obtained by Traverse
NAD 83 (1996 Adjustment)
N- 167028.138
E- 511043.583

2011 The Benton County Surveyor's Office found a broken cast iron monument down 1.4 feet below the road surface on a fence to the east and approximately in the centerline of the road to the west. The cast iron measures 2651.71 feet north and 2690.46 feet south to the section corners. The 1981 distance north was to centerline apparently, but the northeast corner falls north of the centerline of STH 25. Occupation at the 16th corners north and south fit the splits within 4 feet, more or less, and occupation projected from the east through the center of Section 31 fits the corner within 5 feet. Believing the cast iron monument to be the best available evidence of the corner position, a 1/2" by 14" iron pipe capped 19552 was set over it. The 2004 coordinates were verified and reference ties established.