

Statement of Evidence:

C222

Northeast Corner of Section 22, Township 38 North, Range 30 West, Graham Township,
4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

12" Aspen	N 62 E	37 links
12" Aspen	S 45 W	9 links

1914 County Road Book, page 120 contains a road survey by M. J. Cleveland, District Engineer, for State Road No. 7. Survey shows corner found and road run east and south from the corner.

1929 County Engineer's Notebook No. 54 for survey of SAR 12 running west to east terminating at this corner. Corner is in center of roads north, south, and east. Ties:
Cor Conc. Wall NE 36.0'
Cor. Conc. Wall SE 36.3'

1931 County Engineer's Notebook No. 81 for survey of SAR 12 running east to west. Corner is shown as a wood hub in 4-way road intersection with ties:
West End So. Wall Culv. NE 34.1'
West End No. Wall Culv. SE 33.4'
Same notebook shows road survey running north from this corner.

1959 County Engineer's Notebook No. 220 contains a road survey for CSAH 12 running west to east on section line. Corner is shown marked by an iron in center of 4-way road intersection. Note in 1963 shows corner found with same ties as below.

1963 County Surveyor's Record Book 2, page 200 shows an iron at this location with the following reference ties.

P.P.	SW	56.0
T.P.	SE	72.5
T.P.	NW	65.55
15" Spruce	NE	60.05

County Engineer's Notebook No. 285 contains a road survey for CR 22 running south to north on section line. Corner is shown marked by an iron in center of 4-way road intersection with same ties.

1983 David Regan, LS 12236, found a 1" solid pin in at the intersection of the centerlines of County Road 12 and County Road 59. He removed the 1" solid pin and set a cast iron monument at the location of the 1" solid pin and established reference ties. A Certificate of Location (#166044) was filed. (Note: Ties fit 2 PP 1963 ties).

2001 Westwood Professional Services, Inc. found a cast iron monument and established coordinates prior to road overlay project.
County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-180454.925
E-499990.761

2008 Westwood Professional Services, Inc. found a CIM fitting 1983 Regan ties and one 1963 tie. Coordinates obtained by GPS coincide with 2001 coordinates. CIM is accepted as marking the obliterated position for this corner.