

**Statement of Evidence:**

**F352**

Northeast Corner of Section 35, Township 37 North, Range 31 West, Watab Township,  
4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1850 Original US General Land Office survey set a wood post at this location and  
bearing trees were recorded.

|             |            |           |
|-------------|------------|-----------|
| 8" Blk. Oak | S 15 W     | 115 links |
| 8" Blk. Oak | N 74 1/2 W | 106 links |

1961 and 1968 County reference ties:

|           |    |        |
|-----------|----|--------|
| Fen Post  | W  | 30.04' |
| 4" Poplar | SW | 26.27' |
| 5" Oak    | SW | 46.15' |

1969 County Highway information shows corner was marked with a 1" pipe-flush.

|  |    |         |
|--|----|---------|
| Foundation corner of 1 story frame house | NW | 118.0'  |
| 10" Oak                                  | SW | 105.81' |
| P.P.                                     | SE | 125.54' |

1972 County Surveyor's Record Book 1, page 379, shows a RR spike at the corner with  
the following reference ties.

|           |    |       |
|-----------|----|-------|
| 2" Spruce | NW | 35.25 |
| P.P.      | SE | 113.5 |

1981 William Lunser, LS 9394, found a 1/2" iron pipe in the intersection of a  
north/south road and a fence line from the west. He removed the iron and set a  
cast iron monument and filed a Certificate of Location (#158872). Ties check  
reasonably well to house and oak as listed in 1969 and to PP listed in 1972.

2001 Westwood Professional Services, Inc. found a cast iron monument at the location  
of the corner.

2003 Surveying & Engineering Professionals found a CIM.

2008 Westwood Professional Services, Inc. found a CIM at the corner location fitting  
1969 county ties and 1981 Lunser ties. CIM is accepted as marking the  
obliterated location for this corner

County Coordinates obtained by GPS to CIM.

NAD 83 (1996 Adjustment)

N-137456.908

E-473266.271