

**Statement of Evidence:**

**F362**

Northeast Corner of Section 36, Township 37 North, Range 31 West, Watab Township,  
4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

26" Burr Oak	N 56 E	155 links
8" Burr Oak	N 40 W	62 links
6" Blk. Oak	S 78 E	316 links

1923 County Engineer's Notebook No. 32 contains a survey for SR No. 1 running south to north and terminating at this corner. Same ties as in 1926.

1926 County Engineer's notebook 51 and road alignment information (also shown in the County Surveyor's Record Book 1, page 381) note the following reference ties and a distance of 2773.5 feet to the North 1/4 corner Sec 31-37-30.

Corner F.P.	W	29.0
6" R. Oak	SE	59.2

1938 County Engineers' Notebook No. 116 shows survey of SAR 1 running from south to north. Notes show corner being a spike in center of north-south road, SAR No. 4 east, and fence west. Ties:

14" Oak W	36.15'
10" Oak SE	58.2'

Stationing gives distances of 2653.1 feet to the SE corner and 2930.0 feet to the NE corner with a delta angle of 0-25' left.

1961-1968 notes show the corner having the following reference ties.

T.P.	SW	74.45
Twin 10" Oak	W	91.6
P.P.	NE	47.4

Undated notes show a 2" iron pipe down 1 foot with the following reference ties.

Twin 8" R. Oak	SW	89.88
20" R. Oak	SE	141.35
P.P.	NE	47.2

1990 Paul Wellen, LS 10461, found a 3/4" iron pipe at the intersection of the centerline of County Road 1 (running north and south) and the centerline of County Road 4 (from the east) and a tree line (from the west). He set a cast iron monument at the position and established reference ties.

2002 Westwood Professional Services, Inc. found a cast iron monument at the intersection of the centerlines of County Road 1 (running north and south) and County Road 4 (from the east) and a tree line (from the west). Checked for old ties with most destroyed, but Oaks to the SW are still there. Possible remains of original oak BT to the SE needs further review.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-137462.143

E-478581.660

2008 Westwood Professional Services, Inc. found a cast iron monument at the corner location. Further investigation of our 2002 information, we found no conclusive evidence that any remnants of original BT's remain. We did find a twin 14" red oak West 91.6 feet, consistent with 1961-1968 ties. CIM is accepted as marking the obliterated position for this corner. Coordinates obtained by GPS coincide with 2002 position.