

Statement of Evidence:

M221

North Quarter Corner of Section 22, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

1850 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

5" Blk Oak	S 3 ¼ E	89 links
5" Blk Oak	N 23 ¼ W	102 links

1854 RD Lancaster surveyed plat of OSAUKA, which shows this corner being 5 feet east of lot corner No. 23.

Undated Roll F-3, of the MN/DOT alignment plans for TH 10, File No. 34-29, show an I.P. at the corner.

Undated County Surveyor's Record Book 1, page 237, shows a stake at the corner location.

1912 County Highway notes show a stake at the corner with tie:
10" Blk Oak S 10 1/2 E 49 links

1955 This corner is noted on the record plat of HARRIS'S CHANNEL RANC surveyed by M. B. Lang.

1965 The Minnesota Highway Department found a 1/2" iron pin that was 2660.76 feet west of the NE corner of Section 22.

1981 William Lunser, LS 9394, found a 1/2" pinched iron pipe at the corner location. He set a cast iron monument in its place. A Certificate of Location (#173438) was filed.

1991 James Neilsen, LS 11865, found a Minnesota Highway Department cast iron monument and Lunsers ties at the corner location. He filed a Certificate of Location (#216788). The cast iron monument is 2659.33 feet west of the NE corner of Section 22.

2002 Corner destroyed by highway construction.
County Coordinates computed from MN/DOT information:
NAD 83 (1996 Adjustment)
N-115844.019
E-465398.629

2008 Westwood Professional Services, Inc. found a PK nail at the corner. No ties remain from 1981 or 1991 certificates due to road construction. We measured 2659.50 feet to the NE corner of Section 22 which agrees with 1991 Neilsen distance and coordinates obtained by GPS coincide with 2002 MN/DOT position. PK nail is accepted as marking the obliterated position for this corner. PK nail was replaced with PK nail and Benton County Disk.