

Statement of Evidence:

M042

Northeast Corner of Section 4, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey established this corner and set a wood post at this location and bearing trees were recorded.

| | | |
|-------------|------------|-----------|
| 4" Blk Oak | N 26 E | 122 links |
| 6" Blk Oak | N 43 W | 59 links |
| 4" Blk Oak | S 44 W | 1 link |
| 12" Bur Oak | S 57 1/2 E | 130 links |

A line tree is noted as a 10" W Birch East 22.97 chains.

Undated County ties show a 3/4" iron pipe at the corner.

| | | |
|---------|-------|-------|
| 6" Pine | NE 30 | 57.36 |
| 6" Pine | SE 45 | 79.36 |
| 4" Pine | SW 45 | 59.6 |

1981 David Regan, LS 12236, shows a 3/4" iron pipe at the corner location.

1989 William Lunser, LS 9394, found a 3/4" iron pipe. Location of iron pipe was verified using 1981 survey done by David Regan. Removed the pipe and set a cast iron monument in its location. A Certificate of Location (#195965) was filed.

1995 Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a CIM:

N- 132188.135
E- 462525.396

1999 James Kramer, LS 23668, found a cast iron monument and established reference ties. A Certificate of Location (#265887) was filed.

2004 County Coordinates Obtained by GPS to CIM:

NAD 83 (1996 Adjustment)
N- 132188.248
E- 462524.761