

Statement of Evidence:

M102

Northeast Corner of Section 10, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

1850 Original US General Land Office survey established this corner and set a wood post at this location and bearing trees were recorded.

| | | |
|-------------|------------|-----------|
| 10" Blk Oak | S 39 W | 154 links |
| 8" Blk Oak | N 68 1/2 E | 125 links |

1900 County Road Book, page 179, shows road surveyed by John Whilt, County Surveyor, running from south to north. Gives distance of 85.16 chains to the NE corner Sec. 3.

Undated County Surveyor's Record Book 1, page 241, shows an iron with the following reference ties.

| | | |
|------|----|-------|
| P.P. | NE | 30 |
| T.P. | SW | 107.0 |

Roll E-3, of MN/DOT Highway plans for TH 10, show an iron pipe at the corner, 61.3 feet west of the northbound centerline.

1968 County Highway: An iron pin was found and tied off for future road construction.

1974 A cast iron monument was set at this location. (MN/DOT)

1989 Paul Wellen's , LS 10461, notes show a cast iron monument at the corner location.

1990 Minnesota Highway Department found a cast iron monument at this location.

1995 Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a CIM:

| |
|---------------|
| N- 126575.038 |
| E- 467897.150 |

2003 Linda Brown, LS 23682, found CIM and obtained Coordinates by traverse:

NAD 83 (1996 Adjustment)
N- 126575.060
E- 467896.600