

**Statement of Evidence:**

**G311**

North Quarter Corner of Section 31, Township 37 North, Range 30 West, Mayhew Lake Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing tree was recorded.  
5" Blk. Oak                    N 79 1/2 W                    910 links

1926 County Engineer's Notebook No. 51 and Highway alignment records note that this corner was assumed at the intersection of the centerline of the road east/west and a fence line from the north. It also notes a distance of 2773.5 feet to the NW corner of Sec 31 and a distance of 2621.2 feet to the NE corner of Sec 31. The road alignment does not show a delta at this corner.

2002 Westwood Professional Services, Inc. found no evidence of a surface monument prior to road reconstruction. No evidence of fence or occupation lines north or south and no evidence of the GLO BT. The corner was determined to be lost and we set a PK nail at the lost position, being 2780.63 feet from the NW corner Sec 31 and 2617.06 feet from the NE corner Sec. 31. This lost position is within 2 feet of the 1926 highway assumed location based on the 1926 stationing.  
County Coordinates Obtained by GPS - Set PK at the lost position:  
NAD 83 (1996 Adjustment)  
N-137482.257  
E-481362.214

2004 Westwood Professional Services, Inc. set a PK nail and disc at centerline C.S.A.H. #4.  
  
NAD 83 (1996 Adjustment)  
N-137481.571  
E- 481280.501