

Statement of Evidence:

G072

Northeast Corner of Section 7, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as.

14" Blk Oak	N 73 E	236 links
12" Bur Oak	S 2 E	2150 links

1876 County Surveyor's Record Book 1, page 233, shows a road survey by R. Cronk along the east line of Section 7.

1923 County Surveyor's Record Book 1, page 399, and County Engineer's Notebook No. 40, notes the following reference tie to an iron:

Cor FP	E	28.9
--------	---	------

Stationing gives distances of 2629.3 feet to the East $\frac{1}{4}$ corner of Section 7 and 2712.0 feet to the East $\frac{1}{4}$ corner of Section 6 with a deflection angle of 0-20' left (running south to north).

1938 County Engineer's Notebook No. 116 contains a survey for SAR No. 1 that notes the following ties to a spike in road with road west and fence east:

FP	E	29.4	FP	SW	37.1
----	---	------	----	----	------

Stationing gives distances of 2631.1 feet to the East $\frac{1}{4}$ corner of Section 7 and 2712.2 feet to the East $\frac{1}{4}$ corner of Section 6 with a deflection angle of 0-25' left (running south to north).

1980 William Lunser, LS 9394, found a nail and disk in the centerline of a road north/south and a fence line east. He replaced it with a RR spike and filed a Certificate of Location (#158863). Shows distance of 2629.53 feet to the East $\frac{1}{4}$ corner of Section 7.

2008 Westwood Professional Services Inc. found a $\frac{1}{2}$ " open pipe at the centerline of road north/south and a fence line east. Distance to the E $\frac{1}{4}$ Cor. of Sec. 6 measures 2705.24 ft. and distance to the E $\frac{1}{4}$ Cor. of Sec. 7 measures 2631.71 ft., with a deflection angle between said points (south to north) as 0-19'12"-left, which agrees with 1923 measurements. Lunser's RR Spike from 1980 was not recovered. Lunser's tie to said E $\frac{1}{4}$ of Sec. 7 falls 2.13 ft. short of current measurements. The Surveyor accepts the $\frac{1}{2}$ " monument as marking the best evidence and made ties to same.

County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N- 158787.274
E- 484437.709