

**Statement of Evidence:**

**G102**

Northeast Corner of Section 10, Township 37 North, Range 30 West, 4<sup>th</sup> Principal Meridian, (Mayhew Lake Township) Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

10" Aspen	S 16 1/2 E	4 links
12" Aspen	N 53 E	4 links

1938 County Engineer's Notebook No. 122 contains a road survey for CAR 24 running north to south. Notes show corner marked by an oak stake in intersection of roads north-south and east and fence line west. Ties:

14" Oak	NW	80.9
3 <sup>rd</sup> FP	W	38.8

1976 County Highway records dated 6/21/76 show rock 26" below road top and 9" below black dirt. Set iron above rock, 4" below road surface. Ties:

T.P. & Ped.	NE	46.0
PP	SW	48.95
Cor FP	W	169.45

2002 On 10/08/02 Westwood Professional Services, Inc. found a 1/2 " iron pipe with cap marked BWK 10918 in the center of north, south, and east roads and 3 feet north of fence line west. No evidence of Elletson's 1938 ties remain. Took ties to two of the 1976 ties as follows:

Spk & Disc in T.P. & Ped.	NE	47.36'
Spk & Disc in PP	SW	47.33'

On 10/17/02 Westwood Professional Services, Inc. dug with backhoe in road intersection. Down 3.5 feet found a 6" x 8" x 12" pointed stone with wood hubs and 1 1/2" solid iron pin on top. Assume that the stone was set or found by Elletson and therefore we accept the stone as marking the perpetuated position of the corner. Set cast iron monument on top. Corner is 2.0 feet east of found iron pipe. Stone fit 1976 ties.

Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N- 158788.502  
E- 500394.559

2010 The Benton County Surveyor's Office found the cast iron monument set in 2002 and verified the coordinate position. A 1/2" iron pipe was also found 2 feet west of the cast iron, presumably set at the BWK position. The cast iron monument is the accepted corner position.