

**Statement of Evidence:**

**G352**

Northeast Corner of Section 35, Township 37 North, Range 30 West, Mayhew Lake Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

8" Aspen	N 6 E	5 links
6" Aspen	S 6 W	3 links

1926 County Engineer's Notebook No. 51 and road alignment maps by H. G. Elletson note the following reference ties to iron monument.

F.P.	NE	30.0
F.P.	SE	39.0

Fence line north

A delta angle of 01-29 Lt, going from east to west, is noted. Notes show corner at Sta. 11+03.0.

1941 County Engineer's Notebook No. 150 contains a road survey for CAR 25 running south to north on section line. Corner is shown marked by a hub and iron in center of road intersection with SAR 4. Ties same as below in 1949.

1944 County Engineer's Notebook No. 164 contains a road survey for CAR 25 running north on section line from this corner. Corner is shown marked by a hub and iron in center of road intersection with SAR 4. Ties same as below in 1949 with one additional:

14" Elm NE	30.0
------------	------

1949 County Engineer, H. G. Elletson, calls for an iron at this corner with the following reference ties.

14" Elm NE	104.0	
8" W. Oak	SE	69.2

1961 County Surveyor's Record Book 1, page 455, notes an iron monument marked the corner with the following reference ties.

8" W. Oak	SE	69.2
T.P.	SW	130.85
T.P.	SE	46.8

1969 County Engineer's Notebook No. 288 contains a road survey for CSAH No. 25 running north on section line from this corner. Corner is shown marked by an iron in center of road intersection with CSAH No. 4. Ties:

TP	SE	46.9
Stop Sign Post	SE	44.7

1992 Paul Wellen, LS 10461, found a 3/4" solid pipe at the intersection of the centerlines of County Road 4 (running east and west) and County Road 24 (running north and south). He removed the pipe and set a cast iron monument at the location of the iron. A Certificate of Location (#216299) was filed.

2002 Westwood Professional Services, Inc. found a cast iron monument at the intersection of the centerlines of County Road 4 (running east and west) and County Road 25 (running north and south) and located it using GPS prior to reconstruction of the road. No evidence found of previous ties.

County Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment) to CIM  
N-137487.655  
E-505311.307

2004 Westwood Professional Services, Inc. set a PK nail with disc at the intersection of the centerlines of County Road 4 (running east and west) and County Road 25 (running north and south) over previously located cast iron monument.