

Statement of Evidence:

G362

Northeast Corner of Section 36, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

- 1849 Original US General Land Office established corner marked by a wood post with bearing trees noted as:

8" Poplar	N 85 E	44 links
8" Poplar	N 87 1/2 W	89 links
8" Blk Oak	S 66 W	33 links
8" Poplar	S 19 E	53 links

Line trees were noted as a 12" Elm, North, 20.10 chains and a 8" W Oak, South, 20.45 chains.

- 1912 County Engineer's Notebook No. 1, pages 33-37, contains a road survey by M.J. Cleveland for SR No. 10. Notes show no stake found, but set iron mt. on testimony of old resident.

Ties:	NW Cor Barn	S 51 E	43'
	Cor Post	N 35 1/4 E	41'

(Also Engineer's Notebook 2, on page 23)

- 1930 County Engineer's Notebook No. 60 for CR 25 running north-south indicates a nail set for the corner and with County Surveyor's Record Book 1, page 457, notes the following reference ties:

Cor FP	NE	40.3
Cor FP	NW	32.5

- 1935 County Engineer's Notebook No. 87 contains a road survey for SAR No. 4 running from east to west. Corner is shown in 4-way road intersection with same ties as in 1930. Later ties noted as:

FP	NW	50.25'
FP	NE	43.85'

- 1959 County Engineer's Notebook No. 208 contains a survey for CSAH No. 25 running south to north on the section lines. Corner is shown as a spike in center of CSAH No. 4. Ties:

Cor FP	NE	44.15
Cor FP	NW	51.2

- 1992 Sidney Williamson, LS 10918, set a cast iron monument at the location of a found pipe at the centerline of roads north/south/east/west. He filed a Certificate of Location (#213110).

- 2001 Westwood Professional Services, Inc. found a cast iron monument at the centerline of roads north/south/east/west.

- 2004 County Coordinates Obtained by GPS to CIM
NAD 83 (1996 Adjustment)
N- 137562.097
E- 510632.455