

Statement of Evidence:

I023

East Quarter Corner of Section 2, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

| | | |
|-------------|--------|----------|
| 10" Maple | S 43 W | 19 links |
| 18" Bur Oak | S 78 E | 40 links |

1902? County Surveyor's Record Book A, Map No. 33, shows a survey of Section 1 by John Whilt, which notes a distance of 38.67 chains (2552.22 feet) to the NW corner of Section 1 and 39.83 chains (2628.78 feet) to the SW corner of Section 1.

1902? County Surveyor's Record Book 2, page 386, and Record Book A, Map No. 43 shows a second survey of Section 1 by John Whilt. Survey gives a distance of 38.70 chains (2554.20 feet) to the NW corner of Section 1 and a distance of 39.83 chains (2628.78 feet) to the SW corner of Section 1.

1937 County Engineer's Notebook No. 82 contains a road survey for SAR No. 9 running north to south. Notes show corner marked by a spike with town road east. Stationing gives distances of 2563.0 feet to the NE corner and 2652.8 feet to the SE corner.

1962 County Engineer's Notebook No. 269 contains a road survey for CSAH No. 9 running south to north. Notes show corner marked by a spike set in center of road as a POT with town road east. Ties:

| | | |
|--------------------|----|-------|
| PP | NW | 50.0' |
| 1 st FP | SE | 52.9' |

Stationing gives distances of 2633.9 feet to the SE corner and 2562.9 feet to the NE corner.

2001 Westwood Professional Services, Inc. found an iron at the centerline of roads north/south and east/west.

2006 Westwood Professional Services, Inc. tied out the found iron pipe capped 23002 at the intersection of road centerlines. Corner position fits the distance to the north from 1937 and 1962 within a foot and the distance south from 1962 within a foot. No other corner evidence was found.

County Coordinates
NAD 83 (1996 Adjustment)
N-161790.349
E-568304.183