

**Statement of Evidence:**

**I302**

The Northeast Corner of Section 30, Township 37 North, Range 28 West, Maywood Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded:

12" Maple	S 28 E	22 links
10" Lind	N 29 E	45 links

1880's Railroad alignment map shows center of railroad 1224 feet north of the corner on the east line of Section 19.

1912 County Surveyor's Record Book 2, page 442, and Record Book A, Map No. 18, notes a survey by Samuel Chute of Section 29. He notes an iron monument at the corner and a distance of 40.12 chains to the North 1/4 corner Sec 29 and a distance of 40.09 chains to the East 1/4 corner Sec 30.

Undated reference tie:

11" W Elm	S 47 E	80 links (blew down in 1902)
-----------	--------	------------------------------

1929 County Engineer's Notebook No. 57 shows road survey by H. G. Elletson running east from this corner. Corner is shown as an iron pipe with ties:

F.P.	W	23.8'
T.P.	NW	37.7'

1944 County Engineer's Notebook No. 162 contains a road survey for SAR 6 running from south to north on section line. Corner is shown marked by an iron pipe in center of road with CAR 26 east and fence line west. Ties:

TP	NE	49.2'
12" W. Oak	W	148.25'

Stationing gives distance of 1227.05 feet north to center of RR.

1951 MN/DOT alignment map for TH 23 shows 1 1/2 " iron pipe at corner 1369.1 feet south of centerline.

1965 County Surveyor's Record Book 2, page 44, notes the following reference ties to an iron set over a found iron pipe:

TP	SW	74.8
TP	NE	58.25
TP	NW	83.9

(Also noted in Notebook No. 162)

1993 Sidney Williamson, LS 10918, found a 1 1/4" Solid Iron at the centerline of a road north/south/east and fence line west. He replaced it with a cast iron monument and filed a Certificate of Location (#227414).

2001 William Lunser notes per Doc. No. 283115 a distance of 2651.39 feet to the North 1/4 corner Sec 29 and per Doc. No. 283118 a distance of 2648.81 feet to the East 1/4 corner Sec 19.

2007 The Benton County Surveyor's Office found a 3/8-inch rebar at the centerline of roads north-south and east with a fence line to the west. The rebar fits the distances from Mr. Lunser in 2001 within 0.2 feet to the north and east. The distances from 1912 fit within 3.5 feet to the east and 2.5 feet to the south.

County Coordinates  
NAD 83 (1996 Adjustment)  
N-143144.730  
E-547416.809