

Statement of Evidence:

Northeast Corner of Section 1, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office surveyor, Theodore Conkey, set a wood post at this location and bearing trees were recorded.

8" Tamarack	N 16 E	7 links
10" Tamarack	N 72 W	23 links
10" Tamarack	S 4 W	24 links
8" Tamarack	S 73 1/2 E	22 links

Line trees were noted as an 18" Elm South and a 16" Sugar West 21.47 chains.

1899 County Road Book, page 172, shows road surveyed by John Whilt, County Surveyor, west to east on town line and terminating at this corner.

1902? County Surveyor's Record Book A, Map Nos. 33 and 43, shows two surveys of Section 1 by John Whilt.

1916 Mille Lacs County Surveyor's Record Book B, pages 16-19, shows a survey of Section 6, 37-27 by S. L. Kennedy. He notes "probable gov't corner marked by a hub, axle, and 3 rocks in road east-west and fence north.

1921 County Engineer's Notebook 39 lists ties:

Cor. F. P. NE	43.4'	
Cor. F. P. S	32.0'	

Undated County Surveyor's Record Book 2, page 383, shows a post in the centerline of roads with the following reference ties.

10" Maple	N 45 W	41'
Elm	N 66 E	68'
Maple	S 35 1/2 W	56.7'

County Surveyor's Record Book 2, page 386, shows the following reference tie.

24" dead W. Pine	W 51 1/2 E	250 links
------------------	------------	-----------

1955 County Engineer's Notebook No. 202 shows a survey of SAR 5 running west to east on town line. Corner is shown marked by a spike set in center of road with CAR 50 north and fence south. Ties:

P.P.	NW	51.3
T.P.	SW	40.15
Conc. Cor. F.P.	NE	53.5

1994 John Oliver, LS 8194, Mille Lacs County Surveyor, set a cast iron monument based on a distance-distance intersection as determined by "average chain" from Kennedy's survey in Section 6. A Certificate of Location (#244621) was filed. (See Certificate for details)

County Coordinates from John Oliver & Associates by traverse

NAD 83 (1986 Adjustment)

N- 164333.591

E- 573481.576

2001 Westwood Professional Services, Inc. found a cast iron monument at the intersection of the centerlines of County Road 5 (running east and west) and Township Road 68 (running from the north) and established reference ties.

2002 Westwood Professional Services, Inc. located the cast iron monument using GPS.

County Coordinates Obtained by GPS (Cast Iron Monument)

NAD 83 (1996 Adjustment)

N-164334.101

E-573481.164

2009 The Benton County Surveyors Office set a 1/2 inch iron pipe with cap No. 19552 flush with the pavement in place of the found cast iron monument after road construction.