

Statement of Evidence:

I321

North Quarter Corner of Section 32, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

16" W Birch	N 3 1/2 E	49 links
12" Lind	S 6 E	54 links

1912 County Surveyor's Record Book 2, on pages 442 and 443, and Record Book A, Map No. 18, shows a survey of Section 29 by Samuel S. Chute. The lost position for the corner was found not to fit the GLO notes call to the marsh. He interviewed residents and retraced a fence line along north-south 1/4 line in Section 32. Corner was set equal distance between section corners and 83 1/2 links north (55.11 feet) of the straight line between section corners. The corner fell in the road and he set an iron monument. His distances to the section corners shown as 40.50 chains (2673.00 feet).

1940's County Engineer's Notebook No. 160 contains road survey for SAR No. 4 running west to east along the section line. Corner is shown as a 2" hub set in center of road with fence South. Ties:

12" Elm	N	75.65'
10" Twin R. Oak	NW	64.5'

Stationing gives distances of 2671.4 feet to the NW corner and 2674.6 feet to the NE corner with a delta angle of 2-08' right.

1993 Sidney Williamson, LS 10918, found 1/2" solid iron pin and replaced it with a cast iron monument. Filed Certificate of Location (Doc. No. 227426). Distances given on Certificate: 2671.61 feet to NW corner and 2674.82 feet to NE corner.

2011 The County Surveyor's Office found a 1/2 inch rebar 4.5 feet north of centerline of the East-West road with a distance of 2675.22 feet to the Northeast corner, 2671.01 feet to the Northwest corner and 49.8 feet North of line between the Northwest and Northeast corners. The 1/2 inch rebar is accepted as marking the obliterated corner position based on the 1912 resurvey.

County Coordinates
NAD 83 (1996 Adjustment)
N- 137788.269
E- 550110.631