

Benton County Surveyor's Office
Jerome C. Wittstock, County Surveyor
Minnesota License No. 12684

Statement of Evidence:

North Quarter Corner of Section 6, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at the corner location and bearing trees were recorded.

14" B. Ash	S 8 W	16 links
10" B. Ash	N 6 E	35 links

1912 County Surveyor's Record Book 2, page 306 lists ties to a post:

T.P.	S 75-45 W	87 feet
Br. Oak	S 13 E	64 feet

1912 County Engineer's Notebook 2, page 61, is a road survey for SR No. 2 by M. J. Cleveland. Survey was run on section line east-west. Notes show corner post with same ties as above. Stationing gives distances of 2263 feet to the NW corner and 2590 feet to the NE corner of Section 6.

1921 County Engineers' Notebook No. 39 shows survey of road (SR 5) on town line with stationing distances of 2263.4 feet to the NW corner and 2588.7 feet to the NE corner. Deflection angle 55 minutes right (running west to east). Tie:

F.P. South 24.0'

1955 County Engineer's Notebook No. 202 shows a survey of SAR 5 running west to east on town line. Corner is shown marked by a found old wood post and iron set in center of road with fences north and south. 1961 ties are noted to found iron. Stationing gives distance of 2265.8 to the NW corner and 2588.8 feet to the NE corner with a delta angle of 0-40' right.

1955 County Surveyor's Record Book 2, page 396, shows an iron with the following reference ties:

P.P.	NW	41.55 (1955)
T.P.	SW	14.78 (1961)
2 nd F.P.	S	54.6 (1961)
PP	N	38.6 (1961)

1995 On December 26, 1995 William Lunser, LS 9394, found a PK at the intersection of fence lines from the north and south and a road east and west. He replaced the PK with a 1/2" iron pipe and established ties. A Certificate of Location (#234175) was filed. Certificate gives distances of 2588.74 feet to the NE corner and 2265.53 feet to the NW corner with a deflection angle of 0-43-35.

2000 On September 5, 2000 Westwood Professional Services, Inc. found a 1/2" iron pipe at the intersection of County Road 5 (running east and west) and a fence line from the south.

2001 On October 24, 2001 Westwood Professional Services, Inc. found a 1/2" iron pipe over a 1/2" solid pin. Removed the 1/2" iron pipe and set a cast iron monument over the 1/2" solid pin and established reference ties.

2009 Benton County Surveyor's Office set a PK nail with a washer in the pavement in place of the CIM because the CIM was destroyed during road construction in 2008 and 2009. This position fits the historic measurements well, as well as the fence line to the south. Measurements east and west are 2588.76 and 2265.60 respectively. The PK nail was set at the position of the 2001 CIM location, which was accepted as the obliterated corner position.

County Coordinates
NAD 83 (1996 Adjustment)
N-164435.629
E-544711.675