

489192

Certified, Filed and or Recorded on
April 29, 2015 2:20 PM

BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

By: JK

G--V--I


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 2, Township 38, Range 29
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 03/29/2015 found a 1/2" IRON PIPE CAPPED LS 22702

left monument as found lowered monument removed monument (explain)
 On _____ placed on _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota.

Signature Jerome C. Wittstock
Jerome C. Wittstock, PS, CFedS, Benton County Surveyor
License No. 19552

Date: 4/29/2015

Benton County Surveyor's Office
 Jerome C. Wittstock, County Surveyor
 Minnesota License No. 19552

Statement of Evidence:

B021

North Quarter Corner of Section 2, Township 38 North, Range 29 West, Alberta
 Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post and bearing trees noted
 as:

| | | |
|-----------|--------|----------|
| 12" Sugar | S 88 E | 32 links |
| 14" Sugar | N 46 W | 15 links |

Line trees were noted as a 16" Elm East 19.22 chains and
 a 8" Tamarack West 19.77 chains.

2003 No resurvey information was found on this corner in the Benton County records.

2007 The Benton County Surveyor's Office found a 1/2" iron pipe capped 22702 in a
 rock pile with fences north, south, east and west. The found iron fits a split of the
 distances between the northeast and northwest corners of Section 2 with a four-
 way fence intersection at the east sixteenth corner fitting within 2 feet of the split
 to the found iron pipe. The found iron pipe is accepted as marking the corner
 position.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-196448.519

E-533829.324

2010 The Morrison County records were searched and no survey records were found.

2015 The Benton County Surveyor's Office found the 1/2" iron pipe capped 22702 and
 verified the 2007 coordinate position.