

**Statement of Evidence:**

**D332**

Northeast Corner of Section 33, Township 38 North, Range 31 West, East Langola, 4<sup>th</sup>  
Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office survey set a wood post in a mound with pit 8 links south at the corner location.
- 1921 County Surveyor's Record Book shows that Paul Zeese notes an iron at the corner location with the following reference ties.
- |       |    |      |
|-------|----|------|
| TP    | NE | 26.8 |
| Stake | N  | 25.0 |
- Notebook No. 27 gives distance of 2674.2 feet to the North ¼ corner Sec. 33 and 2707.3 feet to the North ¼ corner Sec. 34.
- 1921 County Engineer's notebook 21 contains notes for east-west road that shows corner in road intersection with town road north-south.
- 1972 William Lunser, LS 9394, set a RR spike at the centerline of County Road 2 and at distances proportionate to the Benton County Highway stationing. A Certificate of Location (#133450) was recorded. The following distances are shown on said certificate and are measured from the NE Corner of Section 33:
- |   |
|---|
| 2676.57 feet to the N 1/4 Corner Section 33 |
| 2678.05 feet to the E 1/4 Corner Section 33 |
| 2709.82 feet to the N 1/4 Corner Section 34 |
- 1978 Paul Wellen, LS 10461, measured 2673.55 feet to the East ¼ corner of Section 28.
- 1989 William Lunser set a cast iron monument at the location of a 1/2" iron pipe after verifying the location with existing ties and distances. A Certificate of Location (#195973) was filed.
- 2000 Sam Deleo, LS 40341, found a cast iron monument and filed Certificate of Location (#271527). Gives distances of 2673.06 feet to the East 1/4 corner of Section 28 and 2676.52 feet to the North ¼ corner of Section 33. .
- 2001 Westwood Professional Services, Inc. found a cast iron monument at the intersection of the centerline of County Road 2 and roads north and south.
- 2002 Westwood Professional Services, Inc. located monuments along County Road 2, prior to road construction, using GPS. Set a PK at the location of the found cast iron monument after the road construction.
- County Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N-169655.616  
E-462833.839
- 2004 MN/DOT  
County Coordinates obtained by GPS  
NAD 83 (1996 Adjustment)  
N-169655.589  
E-462833.814