

Statement of Evidence:

C033

East Quarter Corner of Section 3, Township 38 North, Range 30 West, Graham Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office set a wood post at this location and bearing trees were recorded:

3" Birch	N 38 E	39 links
3" Blk Oak	S 23 W	11 links

1908 County Surveyor's Record Book 2, page 164, M.J. Cleveland notes an Iron Mt set at the corner at lost position with the following distances:

41.40 chains (2732.4 feet) to the NE corner Sec 3
41.44 chains (2735.04 feet) to the SE corner Sec 3

1931 County Engineer's Notebook No. 81 for survey of Graham aid road running south to north. Corner is shown as a hub and iron with fence lines running east. Ties:

FP	NE	33.8'
FP	E	26.9'

Stationing gives distances of 2729.9 feet to the SE corner and 2732.0 feet to the NE corner with no delta angle.

1963 County Engineer's Notebook No. 285 contains a road survey for CR 22 running south to north on section line. No corner is shown, but stationing gives distances to 1/4 line fence of 2730.8 feet to the SE corner and 2722.6 feet to the NE corner

1992 Bruce Shepperd, LS 17003, with MN/DNR, searched corner area, including excavation with a backhoe, and found no evidence of a corner marker. He established obliterated corner in center of road on fence lines east and west. He set a 3/4" X 18" iron rod with an aluminum cap marked "DNR Survey Marker" at the corner location and filed a Certificate of Location (#213340). He notes the following distances: 2722.80 feet to the NE corner Sec 3 and 2729.66 feet to the NE corner Sec 10, noting that the corner is 1.74 feet north and 0.94 feet east of the lost position.

2008 Westwood Professional Services, Inc. found a 1" aluminum capped monument (MN/DNR) fitting 1992 Shepperd ties. Monument is accepted as marking the obliterated position for this corner.

County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-193718.383
E-499478.622