

**Statement of Evidence:**

**C051**

North Quarter Corner of Section 5, Township 38 North, Range 30 West, Graham Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office set a wood post at this location and bearing trees were recorded  
12" Blk. Oak                    N 62 1/2 E                    782 links

1888 Morrison County records show H. S. Clyde, County Surveyor, set this corner when he ran the township line for T39N, R30W.

1889 Morrison County Surveyor's Record Book A, page 22, contains a survey of Section 32 by H. S. Clyde where he subdivided Section 32 and calls for the corner set midway between section corners measuring 80.40 chains (5306.4 feet).

1925 Benton County Engineer's Notebook 44, page 10, notes north line of Section 5 run. Stationing from NE corner Section 5 with line run west:  
13+34.8 to fence north  
37+93.0 to oak post  
53+17.0 corner

1925 County Surveyor's Record Book 2, page 168, and Record Book A, Map No. 47, contains a survey of Sections 5 and 8 by Paul Zeese. Survey shows a stake at the corner midway between the sections corners with distance of 2658.5 feet to the section corners.

1997 MN/DOT set the corner at the lost location, midway and on a parallel of latitude, between the section corners with a distance of 2653.17 feet between section corners. Corner fell 4 feet south of an east-west fence line on the edge of a rock pile. James Nielsen, LS 11865, filed a Certificate of Location (Doc. No. 372907) in Morrison County.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-

E-