

Statement of Evidence:

C112

Northeast Corner of Section 11, Township 38 North, Range 30 West, Graham Township,
4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office set a wood post at this location and bearing trees were recorded.

10" Aspen	N 74 W	32 links
10" Aspen	S 13 E	35 links

1908 County Surveyor's Record Book 2, page 162, shows corner was used M.J. Cleveland to set the East ¼ corner of Section 2 lost. Gives the following tie:

3'x4' Stone "S1"	N 68 ½ E	123 links
------------------	----------	-----------

1939 County Engineer's Notebook No. 128 contains survey of CAR 22 running east to west on section line. Corner is shown as a hub set in center of 4-way road intersection. Ties:

FP	SW	60.45
FP	SE	62.95

1962 County Highway notes an iron at the corner with the following reference ties:

PP	NE	54.75
PP	NW	54.2
TP	SW	48.5

1964 County Engineer's Notebook No. 276 contains a road survey for CSAH No. 22 running west to east on section line. Notes show corner marked by an iron in center of road with town road north and south. Ties are the same as listed in 1974 below.

1974 County Surveyor's Record Book 2, page 178, notes the following reference ties to an iron:

PP	NE	55.6
PP	NW	54.85

1988 Bruce Skipton, LS, found a 1" I.M. (axle) at the centerline of roads east/west and north/south which fit with the 1974 ties. He lowered the found monument and set a cast iron monument over it. He filed a Certificate of Location (#191231).

2003 Westwood Professional Services, Inc. found CIM and checked for the old tie to the boulder, but could not find it as it falls in the road ditch and was probably graded out.
County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N- 191145.637
E- 504990.558

2008 Westwood Professional Services, Inc. found CIM fitting 1988 Skipton ties. CIM is accepted as marking the obliterated position for this corner. County Coordinates Obtained by GPS coincide with 2003 position.