

Statement of Evidence:

C122

Northeast Corner of Section 12, Township 38 North, Range 30 West, Graham Township,
4th Principal Meridian, Benton County, Minnesota.

- 1849 Original US General Land Office set a wood post at this location and bearing trees were recorded
- | | | |
|--------------|--------|----------|
| 10" Tamarack | N 68 E | 26 links |
| 10" Tamarack | N 19 W | 25 links |
| 8" Tamarack | S 44 W | 24 links |
| 8" Tamarack | S 31 E | 19 links |
- 1930 County Engineer's notebook No. 79 lists ties to a stake:
- | | | |
|------------------------|----|-------|
| Cor. F. P. | NW | 39.1' |
| Cor. F. P. | SW | 35.3' |
| East side culvert wall | SE | 19.8' |
- 1939 County Engineer's Notebook No. 128 contains survey of CAR 22 running east to west on section line. Corner is shown as a stake in center of 4-way road intersection. Ties:
- | | | |
|-----|----|--------|
| FP | NE | 85.8' |
| Hub | NW | 39.85' |
- 1962 County ties to an Iron inside a post is noted with the following reference ties
- | | | |
|---------------|----|------|
| PP | NW | 58.4 |
| N-end Culvert | NE | 33.5 |
| S-end Culvert | SE | 33.3 |
- 1964 County Engineer's Notebook No. 276 contains a road survey for CSAH No. 22 running west to east on section line. Notes show corner marked by an iron in center of road intersection. Ties:
- | | | |
|----------------|----|------|
| PP | NW | 58.7 |
| Top N end Culv | NE | 44.8 |
| Top S end Culv | SE | 44.1 |
- 1969 Kotsmith notes a stake at the corner with the following reference ties:
- | | | |
|------------------|----|------|
| Cor FP | NW | 39.1 |
| Cor FP | SW | 35.3 |
| E-side Culv Wall | SE | 19.8 |
- 1974 County Surveyor's Record Book 2, page 180, notes an iron placed inside an old post with the following reference ties:
- | | | |
|---------------|----|-------|
| PP | NW | 58.7 |
| Tele Ped Post | NE | 52.65 |
- 1988 William Lunser, LS 9394, found an iron pin and 1 tie at the corner. He replaced it with a cast iron monument and filed a Certificate of Location (#191252).
- 2003 Westwood Professional Services, Inc. found CIM
Coordinates Obtained by GPS to CIM:
NAD 83 (1996 Adjustment)
N- 191251.094
E- 510328.637
- 2011 The Benton County Surveyor's Office found the CIM set in 1988, along with 3 of the reference ties. The iron pin found in 1988 has a history of marking the corner position and the CIM is accepted a marking the iron pin location and is deemed as marking the obliterated corner position. The 2003 coordinates were verified an ties were updated.