

Statement of Evidence:

M101

North Quarter Corner of Section 10, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

1850 Original US General Land Office survey set a wood post for this location and bearing trees were recorded.

10" Bur. Oak	S 52 E	53 links
14" Bur Oak	N 28 E	68 links

1989 Paul Weller's, LS 10461, records show an iron pipe at the corner location.

2002 No resurvey information was found on this corner in the Benton County records.

2003 Westwood Professional Services, Inc. found $\frac{1}{2}$ " iron pipe at the intersection of the centerlines of Scenic Drive NW (running east and west) and occupation lines to the north and south. Analysis of measurements indicates that the pipe was set at the lost position.
County Coordinates by GPS
NAD 83 (1996 Adjustment)
N- 126578.302
E- 465233.575