

Statement of Evidence:

M364

Southeast Corner of Section 36, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

- 1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
16" Bur Oak N 2 3/4 E 481 links, 18" Bur Oak N 14 W 545 links, 14" Bur Oak S 79 W 200 links

This corner is noted on the following recorded plats:

<i>OAKWOOD HEIGHTS (CIM)</i>	3/4/1994	<i>Paul Wellen</i>
<i>OAKWOOD HIEGHTS PLAT 2 (CIM)</i>	9/22/1995	<i>Linda Brown</i>
<i>OAKWOOD HIEGHTS PLAT 3 (CIM)</i>	1/29/1996	<i>Linda Brown</i>
<i>OAKWOOD HIEGHTS PLAT 4</i>	3/5/1997	<i>Linda Brown</i>
<i>CENTER EAST (CIM)</i>	8/22/1992	<i>Sidney Williamson</i>
<i>IVES ACRES</i>	3/17/1986	<i>Paul Wellen</i>
<i>LINCOLN PLACE ADDITION (CIM)</i>	4/16/1985	<i>William Lunser</i>
<i>SOUTHEAST TEN</i>	9/30/1986	<i>Paul Wellen</i>
<i>WOODLAND OAKS ADDITION</i>	9/14/1982	<i>David Regan</i>
<i>AUDITORS 1916 SUBDIVISION</i>	4/18/1916	<i>J.P. Soderstrum</i>
<i>AMERICANNA INN ADDITION</i>		<i>Meinrad B. Torborg</i>
MN/DOT RIGHT OF WAY PLAT NO. 05-16	3/7/2000	<i>David Kohanek</i>

- Undated MN/DOT road alignment plans for TH 10 note an iron pin at the corner and a distance of 167.5 feet to the southeast bound centerline and a distance of 270.1 feet to the northwest bound centerline.

Pre 1940 MN/DOT notes by C. H. West, LS, for TH 95 show square stone monument in place on fence lines east and west. Ties:

12" Oak NE 48.2
12" Oak ENE 40.7
5" Oak SE 44.3

- 1969 Certificate of Location filed in Sherburne County by Delbert Rieke, LS 5094, shows 1" iron pipe found and replaced with a CIM.
- 1998 MN/DOT and Sherburne County Surveyor's Office found and used a cast iron monument at the corner.
- 2000 County Coordinates shown on MN/DOT Right of Way Plat No. 05-16 - CIM
N - 100022.363
E - 479059.363
- 2004 County Coordinates converted from Sherburne County Coordinates on Certificate of Location prepared by Michael Trunk, LS 18434, County Surveyor.
NAD83 (1986 Adjustment)
N - 100022.84
E - 479059.50
- 2008 Westwood Professional Services, Inc. found a cast iron monument at the corner location. CIM fits one remaining tie to Trunk's certificate and agrees with 2000 MN/DOT and 2004 Trunk coordinates. CIM is accepted as marking the obliterated position for this corner.
Coordinates Obtained by GPS to CIM
NAD 83 (1996 Adjustment)
N-100023.104
E-479058.945