

**Statement of Evidence:**

**G093**

East Quarter Corner of Section 9, Township 37 North, Range 30 West, 4<sup>th</sup> Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office surveyor, Edwin James, established corner marked by a wood post with bearing trees noted as.

8" Bur Oak	N 1/2 E	390 links
24" Bur Oak	N 3/4 W	485 links

1892 County Road Book, page 71, shows road laid by out Felix Parrent on east-west  $\frac{1}{4}$  line.

1932 County Engineer's notebook No. 73 contains a road survey by H. G. Elletson for SAR No. 13. Corner is noted in east-west road with town road north and fence south. Corner is a large rock with hole. Ties:

T.P.	NW	30.5'
Cor. F. P.	NE	32.4'

1954 County Surveyor's Record Book 1, page 403, and Engineer's notebook No. 73 notes an iron set over a stone with a hole and the following reference ties

PP	SE	49.95
5 <sup>TH</sup> FP	S	65.4

2003 Survey by Sidney Williamson, LS 10918, shows CIM found at corner with a distance of 2665.21 feet to the NE corner of Section 9.

2006 Westwood Professional Services Inc. excavated a 10-foot x 12-foot x 4-foot deep hole with a Benton County backhoe. A large field stone with drill hole was found down 3 feet under the position of the CIM. A PK nail was set at the centerline of roads north/east/west and fence line south at the position of the found CIM and stone.

Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N- 156164.043  
E-495101.757