

Statement of Evidence:

G113

East Quarter Corner of Section 11, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office established corner marked by a wood post with bearing trees noted as.

18" Bur Oak	S 10 E	21 links
20" Bur Oak	N 43 E	48 links

1890 County Road Book, page 32, contains Surveyor's Report by Felix Parrent stating road laid out on section line. Gives distance of 80.09 chains for the east line of Section 11.

1892 County Road Book, page 71, shows road laid by out Felix Parrent on east-west $\frac{1}{4}$ line.

1932 County Engineer's notebook No. 73 contains a road survey by H. G. Elletson for SAR No. 13. Corner is shown as a spike in 4-way road intersection with ties:

Cor FP	SE	29.6
Cor FP	SW	35.4

1941 County Engineer's Notebook No. 150 contains a road survey for CAR 25 running south to north on section line. Corner is shown marked by a spike set in center of road with center of SAR 13 east and west. Ties same as in 1949. Stationing gives distances of 2659.7 feet to the SE corner and 2675.6 feet to the NE corner with a delta angle of 0-30' right.

1944 County Engineer's Notebook No. 164 contains a road survey for CAR 25 running south to north on section line. Corner is shown marked by a hub set in center of SAR 13. Ties listed are the same as in 1949 below. Stationing gives distances of 2660.7 feet to the SE corner and 2675.2 feet to the NE corner with a delta angle of 0-36' right.

1949 Elletson notes a hub at the corner with the following reference ties:

FP	SE	50.45
FP	NE	55.7

1956 County Surveyor's Record Book 1, page 407, notes a hub at the corner with the following reference ties

Cor FP	SE	29.6
Cor FP	SW	35.4
FP	SE	69.05
FP	SW	60.5

Benton County Surveyor's Office
Jerome C. Wittstock, County Surveyor
Minnesota License No. 19552

1969 County Engineer's Notebook No. 288 contains a road survey for CSAH No. 25 running south to north on section line. Corner is shown marked by a nail set in center of road intersection. Ties:

PP	NW	58.3
FP	SW	69.8
Tel Ped P	SE	47.65

1992 Paul Wollen, LS 10461, found a PK at the centerline of County Road 25 (running north and south) and County Road 13 (running east and west). He replaced it with a cast iron monument and filed a Certificate of Location (#216290).

2008 Westwood Professional Services found a cast iron monument at the centerline of County Road 25 (running north and south) and County Road 13 (running east and west). Left monument as found.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N- 156118.569
E- 505633.990

2011 The Benton County Surveyor's Office reviewed the corner position and the position seems to be consistent with information going back to 1890 forward being located in the centerline of roads in all four directions. The distances north and south fit proportionally with the distances from 1941 and 1944 by approximately 3 feet indicating no substantial movement in the location of centerline of the roads. Since the CIM is located in agreement with the historic data, it is accepted as marking the obliterated corner position.