

Statement of Evidence:

G262

The Northeast Corner of Section 26, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

- 1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as.
- | | | |
|----------|--------|---------|
| 6" Aspen | N 69 W | 6 links |
| 7" Aspen | S 56 E | 6 links |
- 1890 County Road Book, page 32, contains Surveyor's Report by Felix Parrent stating road laid out on section lines west and north from this corner.
- 1941 County Engineer's Notebook No. 150 contains a road survey for CAR 25 running south to north on section line. Corner is shown marked by a hub set in center of road with town road west. Ties same as below in 1949.
- 1944 County Engineer's Notebook No. 164 contains a road survey for CAR 25 running south to north on section line. Corner is shown marked by a hub set in center of road with town road west. Ties same as below in 1949.
- 1949 County Surveyor's Record Book 1, page 431: Elletson notes a hub with the following reference ties:
- | | | |
|----|----|------|
| FP | SW | 46.4 |
| FP | SW | 50.5 |
- 1969 County Engineer's Notebook No. 288 contains a road survey for CSAH No. 25 running south to north on section line. Corner is shown marked by a spike set in center of road with town road west. Notation in 1975 states placed iron with same ties as below.
- 1975 County Surveyor's Record Book 1, page 433, notes an iron with the following reference ties:
- | | | |
|----|----|------|
| FP | SW | 49.4 |
| PP | NW | 58.4 |
- 1990 Paul Wellen, LS 10461, found a 1" solid pin at the intersection of the centerline of County Road 25 (running north and south) and 75th Street NE (running west) and a field line (from the east). He set a cast iron monument over the iron and filed a Certificate of Location (#200722). He noted above reference ties were gone.
- 1999 Doc No. 283107 notes a distance of 2691.18 feet to the East ¼ corner Sec 23.
- 2009 The Benton County Surveyor's Office found a cast iron monument 0.4 feet below the road surface. The monument measures within 1.6 feet of the 1941 and 0.6 feet of the 1999 distance a half mile north and within 1.2 feet of the 1941 distance a half mile south. The cast iron monument is accepted as the best available evidence of the corner location.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-142731.719
E-505403.344