

Statement of Evidence:

G332

Northeast Corner of Section 33, Township 37 North, Range 30 West, Mayhew Lake Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

5" Aspen	S 59 E	330 links
12" Blk. Oak	S 40 W	1095 links

1926 County Engineer's notebook No. 51 and road alignment maps note the following reference ties (also shown in the County Surveyor's Record Book 1, page 451) to the section corner:

F.P.	SW	29.3
F.P.	SE	21.8

Plans also note a distance of 2637.5 feet to the North 1/4 corner of Sec 34 and a distance of 2693.0 feet to the North 1/4 corner of Sec 33. A delta angle of 00-18 Right is shown when going from east to west.

2001 William Lunser, LS 9394, notes a distance of 2621.09 feet to the East 1/4 Corner of Section 33, a 1/2" iron pipe, per Certificate of Location (#293105).

2002 Westwood Professional Services, Inc. found a cast iron monument in the centerline of CSAH No. 4 (running east and west). We located the monument using GPS prior to road reconstruction and found that the delta angle was 00-14-24 Right (moving east to west) and that the distance to the North 1/4 corner of Sec 33 is 2680.09 feet and that the distance to the North 1/4 corner of Sec 34 is 2652.46 feet. Comparison to 1926 stationing along the CSAH 4 project indicates the corner was 15.75 feet east of the CIM in 1926. We found no record of who set the CIM.
County Coordinates Obtained by GPS to CIM
NAD 83 (1996 Adjustment)
N-137518.512
E-494733.786

2003 Westwood Professional Services, Inc. set a PK nail in bituminous at centerline C.S.A.H. #4 over a cast iron monument.
NAD 83 (1996 Adjustment)
N-137518.512
E- 494733.786