

Statement of Evidence:

I312

Northeast Corner of Section 31, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

- 1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.
- | | | |
|-------------|----------|----------|
| 10" Blk Ash | S 79 ½ W | 38 links |
| 14" Lind | S 34 E | 31 links |
- 1901 County Surveyor's Record Book A, Map No. 42, shows a survey of Section 31 by John E. Whilt.
- 1912 County Surveyor's Record Book 2, on pages 442 and 443, and Record Book A, Map No. 18, shows a survey of Section 29 by Samuel S. Chute. Corner is shown marked by an iron monument.
- 1912 County Engineer's Notebook 1, pages 37 to 42 contains a road survey for State Road No. 10. Notes corner in center of road with ties:
- | | | |
|-----------|----|------|
| Cor. Post | SW | 56.5 |
| Cor. Post | NW | 54 |
| Cor. Post | NE | 56 |
| Cor. Post | SE | 54.3 |
- 1938 County Engineer's Notebook 113 contains a road survey for State Road No. 4 running west from this corner. Notes corner as an iron in 4-way road intersection with ties:
- | | | |
|-------|----|-------|
| TP | SE | 41.1' |
| Guy P | NE | 43.8' |
- 1940's County Engineer's Notebook No. 160 contains road survey for SAR No. 4 running east from this corner. Corner is shown as an iron pipe in center of road intersection. Same ties listed in County Surveyor's Record Book 2, page 446:
- | | | |
|------------|----|-------|
| Conc. Curb | NE | 28.2 |
| Conc. Curb | SE | 28.6 |
| 12" Elm | NW | 197.5 |
| 16" Bass | NW | 153.1 |
- Page 448 other ties:
- | | | |
|----|----|------|
| TP | NE | 42.7 |
| TP | SE | 39.8 |
- 1944 County Engineer's Notebook No. 162 contains a road survey for SAR 6 running south to north on section line. Corner is shown marked by an iron pipe in center of road intersection. Same ties as Notebook No. 160.
- 1993 Sidney Williamson, LS 10918, found 1" solid iron pin and replaced with a CIM. Filed Certificate of Location (No. 227416).
- 2008 The Benton County Surveyor's Office found a Cast Iron Monument at a four-way road intersection. Distance west fits 1944 distance within a foot.
- County Coordinates
NAD 83 (1996 Adjustment)
N-137790.805
E-547439.623

NOTE: Assume iron pin found in 1993 is from County Highway Department. Should check for old ties.