

**Statement of Evidence:**

**I232**

Northeast Corner of Section 23, Township 37 North, Range 28 West, Maywood Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established this corner and set a wood post and bearing trees were recorded as follows:

12" Tamarac	N 50 E	55 links
12" Tamarac	S 68 ½ E	64 links

1932 County Engineer's Notebook No. 80 for survey of SAR 9 running south to north. Corner is shown as a hub and stake in center of road intersection. Ties:

TP	SW	33.0'
3 <sup>rd</sup> FP	SW	55.3'

1960 County Surveyor's Record Book 2, page 430, shows County Highway Department notes that state: "found old stake, placed iron over stake".

1961 County Engineer's Notebook No. 234 contains survey for CSAH 9 running south to north on section line. Notes show corner marked by an iron in center of road with same ties as below in 1963. Town road runs east and west.

1963 County Highway Department lists the following ties to found corner:

PP	NE	41.3
Anchor Pole	NW	50.8
TP	SW	40.05

2002 Westwood Professional Services, Inc. found a ½ " solid iron pin down 1.5 feet in the intersection of the centerlines of County Road 9 (running north and south) and 85<sup>th</sup> Street NE (running east and west). Only one 1963 tie remained; the Anchor Pole to the NW and it checked reasonably well. The pole has been cut off and is leaning slightly to the east. Accepted the found iron pin as being the best evidence of the obliterated corner position based on the 1960 notes.

On 10/8/02, Westwood Professional Services, Inc. set a cast iron monument over the found iron pin and took ties. Filed Certificate of Location (Doc. No. 291184).

2003 County Coordinates by GPS  
NAD 83 (1996 Adjustment)  
N- 148516.519  
E- 568482.138