

Statement of Evidence:

I101

North Quarter Corner of Section 10, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established this corner and set a wood post for the corner and bearing trees were recorded.

9"	Tamarack	N 67 E	7 links
8"	Tamarack	S 60 W	9 links

1913 County Surveyor Record Book, pages 44 to 47, contains a survey in Section 10 by J. A. Stanton. Survey shows corner falls in a swamp and no corner found. Notes a distance of 2653 feet from the NE corner Sec 10 to approximate corner.

1915 County Surveyor's Record Book 2, pages 314 and 315, and Record Book A, Map No. 9, shows J. P. Soderstrum did a survey of Section 3. Notes show a distance of 80.41 chains between the SW and SE section corners. No record of finding the 1/4 corner is noted and it appears he established it lost, midway between section corners. Map No. 9 shows a stake midway.

1999 David Regan, LS 12236, information gives a distance of 5309.55, more or less, between section corners. He shows corner 2633.00 feet west of the NE corner of Section 10 and 2676.85 feet east of the NW corner of Section 10 or 21.8 feet east of the lost position.

2003 Westwood Professional Services, Inc. measured 5308.82 feet between section corners, which compares well with Soderstrum's 80.41 chains (5307.06 feet).

2006 Benton County Surveyor's Office measured 5309.38 between section corners which compares well with Westwood's distance of 5308.82. A metal T-post was set at the lost position being 2654.69 feet from both section corners and online between both section corners. This position agrees with the County Surveyor's Record in 1915.

County Coordinates
NAD 83 (1996 Adjustment)
N-158963.639
E-560488.165

Benton County Surveyor's Office
Jerome C. Wittstock, County Surveyor
Minnesota License No. 19552