

Statement of Evidence:

D151

North Quarter of Section 15, Township 38 North, Range 31 West, East Langola Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey established this corner and set a wood post for the corner location with the following bearing trees marked:

| | | |
|-----------|------------|-----------|
| 8" W. Elm | N 18 1/2 E | 44 links |
| 6" W. Elm | N 24 W | 110 links |

1916 County Surveyor's Record Book 2, page 82, and Record Book A, Map No. 8 shows a survey of Section 10 by J.P. Soderstrum. He found no evidence corner. He notes a fence corner found 41.17 chains east of the SW corner of Section 10, 43 links north of his line. Map 8 shows post at corner a distance of 41.10 chains (2712.6 feet) to the SE corner Sec. 10 (Iron) and a distance of 41.30 chains (2725.8 feet) to the SW corner of Sec. 10 (Stone).

No Date County Surveyor's Record Book 2, page 104 notes a post and a fence corner at the corner location.

1961 MN/DNR survey crew ran north line of Section measuring 5409.60 with 1/4 corner determined at the lost position midway. Nothing set at the corner.