

Statement of Evidence:

D362

Northeast Corner of Section 36, Township 38 North, Range 31 West, East Langola Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post in a mound with pit 6 links south at the corner location.

1914 County Road Book, page 80 contains a road survey by M. J. Cleveland, District Engineer, for State Road No. 5. Survey starts at this corner and runs west.

Undated County notes call for an iron at the corner with the following reference ties.

N&D 8" N. Pine	NW	81.23
N&D TP	NE	52.45
N&D 8" N. Pine	SW	62.91
N&D PP	SW	64.84

1921 County Engineer's Notebook No. 21 shows iron monument at corner with town road north-south. County Surveyor's Record Book 2, page 152, shows an iron at the corner with the following reference tie.

TP NW 45.8

1940 County Engineer's Notebook No. 133 contains a road survey for CAR No. 41 running south to north. Corner is shown as an iron in the center of SAR 2. Ties:

TP	NW	45.8'
Snow Fence marker	NE	37.9'

1978 Ronald Engelmeyer, LS 13334, found a 1/2" iron pipe and filed a Certificate of Location (#151569).

2001 Westwood Professional Services, Inc. found a nail in a 1/2" iron pipe at the intersection of the centerlines of County Road 2 (running east and west) and County Road 78 (running north and south). We found nothing below the pipe. Pipe checked reasonably well with some of the ties listed above that are still in place.

2002 Westwood Professional Services, Inc. located monuments along County Road 2, prior to road construction, using GPS. Westwood Professional Services, Inc. set an iron capped #12684 at the location of the 1/2" pipe after road construction and filed Certificate of Location (Doc. No. 293720).
County Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-169683.560
E-478930.398