

Statement of Evidence:

H113

East Quarter Corner of Section 11, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

6" Tamarack	S 54 E	23 links
6" Tamarack	N 13 1/2 W	11 links

2002 No resurvey information was found on this corner in the Benton County records.

2008 The County Surveyor's Office searched and found a 1/2" capped iron pipe at the centerline of a north-south gravel road (125th Avenue N.E.) and on line with a west fence line. Distances to the NE and SE Corners measure 2637.37 ft. and 2605.75 ft., respectively. Corner falls 5.81 ft. west of a straight line. The position fits occupation and is accepted as the best evidence. Ties were made.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-156343.731

E-537285.822