

Statement of Evidence:

H203

East Quarter Corner of Section 20, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

6" Tamarack	N 50 1/4 E	8 links
10" Tamarack	S 61 1/2 W	20 links

1949 County Highway Engineer's Notebook No. 169 contains road survey for CAR 37 running from south to north on the section line. Corner is shown marked by a hub set in the center of road with fence line east. Ties are same as listed below. Stationing gives distances of 2666.3 feet to the SE corner and 2671.6 feet to the NE corner with corner being a POT.

1949 County Highway information by H. G. Elletson notes the following reference ties to a hub:

24" Elm	NE	197.2
3 rd FP	E	48.1

2009 Westwood Professional Services located a PK Nail in the north-south centerline on line between the northeast and southeast corners of Section 20. The PK Nail measures 2667.87 to the northeast and 2669.32 to the southeast corners of the section, fitting the 1949 overall mile within 1 foot, but being 3.5 feet off proportionally at the east quarter corner. A crooked fence to the east was found but no exact location could be determined from it. Since the distance for the overall mile agrees within 1 foot, and there is no record of the PK Nail, a 1/2" x 14" iron pipe capped 19552 was set at the 1949 prorated location.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-145665.005
E-521325.761