

**Statement of Evidence:**

**H061**

North Quarter Corner of Section 6, Township 37 North, Range 29 West, Gilmanton Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

12" W Oak	N 35 E	8 links
10" W Oak	S 17 E	24 links

A line tree was noted as a 12" Poplar West 21.28 chains and a 10" W Oak East 18.00 chains.

Undated County Surveyor's Record Book 2, page 298, notes the following reference ties:

TP	SW	87
B Oak	SE	64

2004 Danny Kron, LS 42621, set a 1/2 " iron pipe at the lost position, which fit center of east-west road and fence line south. Found no evidence of the undated ties.

County Coordinates Obtained by SEPI (traverse):

NAD 83 (1996 Adjustment)

N- 164323.265

E- 513683.738

2011 The Benton County Surveyor's Office found a 1/2-inch iron pipe with broken cap, presumably set in 2004 by Kron. The iron falls on a fence to the south and is 3 feet north of the east-west centerline of 115<sup>th</sup> Street NE. Accepted the found iron pipe as marking the corner position and drove found iron down and set 1/2-inch by 14-inch iron pipe capped 19552 over it. The 2004 coordinates were verified.