

Statement of Evidence:

H091

North Quarter Corner of Section 9, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

| | | |
|-------------|--------|----------|
| 9" Tamarack | N 47 W | 21 links |
| 7" Tamarack | S 11 E | 9 links |

1997 William Lunser, LS 9394, accepted fence corner of fences running west and south as marking the obliterated position and set a ½ " iron pipe. He filed a Certificate of Location (Doc. No. 283109). He gives a distance of 2627.10 feet to the NW corner and 2560.54 feet to the NE corner.

2009 The Benton County Surveyor's Office found a 1/2-inch iron pipe capped 9394 on the north end of a fence south with a partially down fence running to the west. The iron pipe measures within 0.1 feet of the 1997 distance to the west and measures 2556.56 feet to the east to a found 8-inch square granite stone with a north-south down fence at the east sixteenth falling 10 feet west of a split. The corner position falls 22 feet north and 35 feet east of the lost position.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)
N-158929.252
E-524194.676

2010 Discussed this corner position with Sam DeLeo of KLD, owner of Lunser's records. Based on the discussion of parole evidence collected and other efforts completed in 1997, the corner is accepted as marking the obliterated corner location.