

Statement of Evidence:

H111

North Quarter Corner of Section 11, Township 37 North, Range 29 West, Gilmanton Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked with a wood post with bearing trees noted as:

10" Sugar	N 62 E	27 links
20" Sugar	S 62 W	18 links

No Date (Old) County Surveyor's Record Book 1, page 463, shows D. B. Cannon measured 79.10 chains for the north line of Section 11.

1992 Paul Wollen, LS 10461, set a cast iron monument at the centerline of roads east/west and a fence line and tree line south. He filed a Certificate of Location (#216305).

2012 Benton County Surveyor's Office found a cast iron monument at the centerline of the east/west road and fence line to the south. The monument measures 2660.20 feet to the NW corner and 2664.72 feet to the NE corner of Section 11. The found reference ties matched the ties shown on Certificate of Location (#216305). The monument was accepted as the obliterated quarter corner.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N- 158931.72
E- 534699.41