

Statement of Evidence:

F043

East Quarter Corner of Section 4, Township 37 North, Range 31 West, Watab Township,
4th Principal Meridian, Benton County, Minnesota.

- 1850 Original US General Land Office survey set a wood post in a mound with pit 6 links east for the corner location.
- 1945 MN/DOT alignment and right of way map for US Highway 10 shows corner assumed in north-south road. No information about the corner is shown.
- 1975 M.W.Carley survey notes show a 1" iron pipe was found at the corner.
- 1975 Survey by H.G. Elletson, LS 728, shows an IM at the corner with a distance of 2883.70 feet to the NE corner of Section 4.
- 1988 William Lunser, LS 9394, set a cast iron monument at the found 1" iron pipe location that he had previously found in 1987 and filed a Certificate of Location (#191254). He notes distance to the NE corner of Sec 4 is 2882.29 feet and the distance to the SE corner of Sec. 4 is 2659.05 feet.
- 2002 Westwood Professional Services, Inc. found CIM per Lunser's certificate with 3 ties checking.
County Coordinates Obtained by GPS to CIM
NAD 83 (1996 Adjustment)
N-161417.581
E -462831.156
- 2008 Westwood Professional Services, Inc. found CIM at the corner location. CIM fits one remaining Lunser tie and coordinates obtained by GPS coincide with 2002 position. CIM is accepted as marking the obliterated position for this corner.