

Certified, Filed and or Recorded on  
OCT. 18, 2005 AT 11:29:00AM

Signed: VA  
MARILYN J NOVAK G J I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER


## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 12, Township 36 North, Range 29 West,  
4th Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_  
DATE

left monument as found     lowered monument     removed monument (explain)  
 On 8/4/2005 placed a Cast Iron Monument  
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Mary A. Stein

Date 8/18/2005

License No. 12684

Title  Land Surveyor  Professional Engineer  County Surveyor  County Engineer

Statement of Evidence:

K123

East Quarter Corner of Section 12, Township 36 North, Range 29 West, St. George Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post with bearing trees noted as.

10" Basswood	N 12 E	60 links
6" Elm	S 54 W	38 links

A line tree was noted as a 16" Blk Ash South 24.72 chains and a 10" Blk Ash North 20.69 chains.

1987 Paul Wellen, LS 10461, set a cast iron monument at fence corner, with fences running west and south. He filed a Certificate of Location (Doc. No. 182954).

2005 WSN briefly searched corner area and did not find the CIM.

County Coordinates computed to Wellen's position based on 1987 survey using distance from the NE corner and angle from the North 1/4 corner.

NAD 83 (1996 Adjustment)

N- 124693.009

E- 542575.863

Conducted another search of the area and did not find the CIM set by Wellen. Fence and field lines have been removed and the corner area falls in a plowed field and CIM has been destroyed. Coordinates are the best evidence of the obliterated position and the corner needs to be reset.

On 8/4/05 set new cast iron monument down 2 feet below plow line.

## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 12, Township 36, Range 29, 4th P.M.  
 STATE OF MINNESOTA, County of Benton


At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_  
 DATE

left monument as found,  lowered monument,  removed monument (explain)

On 4/13/87 placed a Cast Iron Monument  
 DATE

## SKETCH OF REFERENCE TIES



1 8 2 9 5 4

OFFICE OF  
 BENTON COUNTY RECORDER  
 BENTON COUNTY, MN  
 CERTIFIED TO BE FILED  
 AND/OR RECORDED ON

ALICE G. ENGELMEYER  
 COUNTY RECORDER

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

5/5/87

DATE

Registration No. 10461

Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
 County of \_\_\_\_\_

I hereby certify that this document was filed in the Co. Recorders office at \_\_\_\_\_ M. on the \_\_\_\_\_ day of \_\_\_\_\_ A.D., 19 \_\_\_\_\_.  
 County Recorder \_\_\_\_\_  
 By \_\_\_\_\_, Deputy  
 DOCUMENT NO. \_\_\_\_\_