

Certified, Filed and or Recorded on
Nov. 07, 2008 AT 02:26PM

Signed: *JW*
MARILYN J NOVAK *SV*

BENTON COUNTY MINNESOTA

MARILYN J NOVAK

COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 11, Township 36N, Range 29W
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10/14/08 found a 1/2" IRON PIPE CAP # 19552 UP 0.5'

left monument as found lowered monument removed monument (explain)

On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature *Jar W. Ols*
Deputy Benton County Surveyor
License No. 145872

Date: 11/06/2008

Benton County Surveyor's Office
Jason W. Oberg, Deputy County Surveyor
Minnesota License No. 45872

Statement of Evidence:

K113

The East Quarter Corner of Section 11, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey established corner marked by a wood post with bearing trees:

14" Elm	N 61 E	68 links
12" Maple	N 56 W	19 links

2002 No resurvey information was found on this corner in the Benton County records.

2008 The County Surveyor's Office searched and found a $\frac{1}{2}$ " iron pipe capped "19552" at 0.5' above the surface along an east-west fenceline. The location is at the intersection of a straight line between the NE Cor. and the SE Cor. of Sec. 11 and the east-west fenceline. The surveyor accepts the position and set ties to same.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-124753.262

E-537410.165