

Benton County Surveyor's Office
Nathan H. Carlson, Deputy County Surveyor
Minnesota License No. 45873

Statement of Evidence:

K052

Northeast Corner of Section 5, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

- 1849 Original General Land Office survey established this corner set a wood post at this location and bearing trees were recorded.
- | | | | | | |
|-----------|--------|----------|-------------|--------|----------|
| 12" W Oak | N 30 E | 39 links | 14" W Oak | N 65 W | 19 links |
| 6" Elm | S 16 W | 38 links | 6" Ironwood | S 86 E | 17 links |
- No Date County Surveyor's Record Book 1, page 93, notes the following reference ties to an oak stake and rock:
- | | | | | | |
|----|----|------|----|----|------|
| TP | SW | 57.4 | TP | NW | 96.4 |
|----|----|------|----|----|------|
- Page 525 contains additional ties:
- | | | | | |
|-----------------------------|---------------|--------|----|-------|
| 4.0 foot diameter flat rock | 7.3 feet east | 6" Oak | NE | 42.05 |
| Fen. P. | NW | 38.5 | | |
- 1894 County Road Book, page 84, shows road surveyed by Felix Parrent, County Surveyor, on east-west town line. Gives distance of 80.26 chains for the north line of Section 5.
- 1912 County Engineer's Notebook 2, page 49, contains a survey for State Road No. 9 by M. J. Cleveland. Ties:
- | | | | | | |
|------|----|-----|------|----|-----|
| T.P. | NW | 49' | T.P. | NE | 41' |
|------|----|-----|------|----|-----|
- 1913 County Surveyor's Record pages 34 and 35: J. A. Stanton found corner preserved by Mr. Galmault from original survey.
- 1949 County Highway Engineer's Notebook No. 169 contains road survey for CAR 37 running from south to north on the section line. Corner is shown marked by a stake and stone in the center of road with town road west. Ties are the same as listed in County Surveyor's Record Book 1, page 525:
- | | | | | | |
|----|----|------|----|----|-------|
| TP | SW | 58.4 | TP | NW | 48.55 |
|----|----|------|----|----|-------|
- (Later notation shows same ties to concrete R/W monuments as below by West.)
- 1949 C.H. West, LS 932, found a stone and rotted oak fence post. He replaced it with a 8" X 30" round concrete monument with the following reference ties
- | | | |
|--------------------------|----|-------|
| 2 1/2" X 5" R/W Monument | NE | 118.8 |
| 2 1/2" X 5" R/W Monument | SW | 103.1 |
- Alignment map for TH 23 shows corner in north-south road and road west 114.0 feet north of the centerline of TH 23. (County Highway notebook 1, page 67 shows same ties.)
- 1978 Ronald Engelmeyer, LS 13334, found a 1/2" square iron pin and left it as was. He filed a Certificate of Location (#151557). A tie of 118.43 feet is shown to a 3" diameter R/W monument to the NE.
- 2003 Westwood Professional Services, Inc. found a hub and spike and located it by GPS.
Note: Need to check for previous ties and monument. Do not use coordinates without verification.
County Coordinates obtained by GPS to Spike
NAD 83 (1996 Adjustment)
N- 132221.639
E- 521134.121
- 2004 MN/DOT found 1949 concrete monument.
County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N- 132221.637
E- 521133.860
- 2010 Westwood Professional Services, Inc. found a CIM, established reference ties and verified the 2004 MnDOT coordinates.