

Statement of Evidence:

M093

East Quarter Corner of Section 9, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

1850 Original US General Land Office survey set a wood post for this location and bearing trees were recorded.

6" Blk Oak	N 77 E	157 links
4" Blk Oak	N 48 W	116 links

This corner is noted on the following recorded plats:

<i>BRENDA LEE ADDITION</i> (CIM)	5/29/1992	Vernon H. Bartz
<i>FRITZ ADDITION</i> (CIM)	5/7/1987	Sidney Williamson
<i>GUZMAN SARTELL ADDITION</i>	6/21/1982	Sidney Williamson

1987 Sidney P. Williamson, LS 10918, set a cast iron monument at the corner location. This corner was identified in the 1905 Plat of the Townsite of Sartell. This plat has been perpetuated since that time and provides conclusive evidence for the restoration of this obliterated corner. A Certificate of Location (#181081) was filed.

2002 No resurvey information was found on this corner in the Benton County records.

2003 Westwood Professional Services, Inc. found a ½ " iron pipe at the corner. Corner now falls in east-west street and CIM set in 1987 has been destroyed. Distances north and south to section corners and angle at this corner checked well with Paul Wellen, LS 10461, information in 1989.

County Coordinates Obtained by GPS:

NAD 83 (1996 Adjustment)
N- 123832.000
E- 462581.771

2008 The County Surveyor's Office searched and found a ½ inch open iron pipe at the centerline of an east-west road (9th Street N.E.). Tie distances to a NE ¾" iron pipe, a SE power pole, and the NE corner of a SW house check well with Williamson's 1987 record. The position gives distances to the NE Cor. and SE Cor. of 2749.61 feet and 2640.01 feet respectively. Surveyor accepts iron pipe position and updated ties. Coordinates obtained by GPS agree with those reported by Westwood in 2003.