

Statement of Evidence:

M113

East Quarter Corner of Section 11, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

1850 Original U.S. General Land Office survey established this corner and set a wood post at this location with bearing trees recorded:
20" Black Oak N 81 1/2 E 159 links

1984 William Lunser, LS 9394, set a cast iron monument on a line between the NW and the SW corners of Section 12 and equal distances from each and filed a Certificate of Location (#173421).

2002 No resurvey information was found on this corner in the Benton County records.

2003 Linda Brown, LS 23682, found CIM and obtained County Coordinates by traverse:
NAD 83 (1996 Adjustment)
N- 123842.691
E- 473277.016

2008 The County Surveyor's Office searched and found a cast iron monument $9.5 \pm$ feet east of the centerline of a north-south road (County Road No. 57) and $6 \pm$ feet north of the centerline of an east gravel driveway. The position gives distances from the NE Cor. and the SE Cor. of 2658.11 feet and 2657.96 feet and is on a straight line between said corners, which agrees with Lunser's 1984 report. Position agrees with long standing surrounding occupation. Surveyor accepts the CIM as best evidence of obliterated corner and updated ties.

County Coordinates obtained by GPS (CIM)
NAD 83 (1996 Adjustment)
N-123842.582
E-473277.167